

Continuous Safety Services Site Visit Report

The electrical systems of the site listed below were inspected on 2018/09/05 by Electrical Inspector Luciano Milantoni and the findings from that inspection are identified on this report. In addition, you will also find an Outstanding Defect Report attached that outlines any electrical defects that are still in our records as uncorrected. Please advise Luciano Milantoni once you have corrected any defects that were found.

Customer Information	Site Information
i3 INTERNATIONAL 780 BIRCHMOUNT RD U16 TORONTO, ON Attn: JACK HOANG	i3 INTERNATIONAL INC U14-16 780 BIRCHMOUNT RD TORONTO, ON Attn: JACK CSSL HOANG

Issue Date: 2018/09/05
Purpose of Visit: Inspection
Visit Contact: DALE

Inspector Name: Luciano Milantoni
Inspector Cell #: 647-404-9304
Inspector Email: LUCIANO.MILANTONI@ELECTRICALSAFETY.ON.CA

Recommendations

1	Risk Factor N/A	Notification #: 20474737 Rule Reference: 02-003&02-006 Logbook Review Defect Location:	Issue Date: 2018-09-05 Defect Status: Completed Defect #: 2	Initial if corrected
	Code Rule: An audit of the electrical work recorded in the logbook was conducted and there were no defects identified.			
	Inspector Comments:			
2	Risk Factor N/A	Notification #: 20474737 Rule Reference: 02-004(a) No defects Defect Location:	Issue Date: 2018-09-05 Defect Status: Completed Defect #: 3	Initial if corrected
	Code Rule: No defects were identified.			
	Inspector Comments:			

Thank you for giving us the opportunity to help you improve the safety of your facility. Your attention to these hazards, defects and recommendations will ensure continued safety on your premises. Should you have any questions regarding the items listed in this report, please do not hesitate to contact us.

Can your employees identify electrical hazards in the workplace? Do your electrical workers and maintenance staff understand the requirements of the OESC? ESA encourages supervisors and workers to continually improve their knowledge and follow safe work practices. Visit www.esasafe.com & choose "Safety and Technical Training" for dates and locations of workshops in your area or contact us at 1-877-854-0079.

Outstanding Defect Summary Report

The following list of defects are still outstanding from our previous inspection visit(s). These items not only represent contraventions to the Ontario Electrical Safety Code but they also expose workers and employees to an electrical safety risk. As per Rule 2-018 of the Electrical Safety Code, all defects regardless of the risk factor assigned must be corrected as soon as possible. Please notify the Electrical Inspector by email indicating which defects have been corrected. Alternatively you can initial corrections and fax this report to 905-712-7886.

Customer Information	Site Information
i3 INTERNATIONAL 780 BIRCHMOUNT RD U16 TORONTO, ON Attn: JACK HOANG	i3 INTERNATIONAL INC U14-16 780 BIRCHMOUNT RD TORONTO, ON Attn: JACK CSSL HOANG
Outstanding Defects	

There are currently no outstanding defects from previous visits. Please refer to the previous pages of this report to review any electrical deficiencies that were found on the most recent inspection visit.