



Re: Camera Color Balance Adjustment on LD16 encoder


To all of our customers and partners;



Follow the instructions below to fine-tune camera color balance settings on LD16 encoder.


1. Launch the LD16 web GUI from ACT or from the SRX-Pro List.



2. Log into the Encoder using the administrator credentials. Username: **i3admin**.



3. In the Channel List, click on the **Play**  icon to bring each camera into the Full Screen mode.
4. Click on the Color icon  to bring up the Color panel.
For best picture quality, increase Brightness and decrease Saturation until satisfied with the image.
5. When done, close the encoder GUI page.



Please contact technical support if you have any questions or issues.
Email: support@i3international.com
Tel.: 1.877.877.7241
i3 International Inc.

CONTACT US

www.i3international.com

Toll free: 1.866.840.0004

Tel: 416.261.2266

Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16

Toronto, Ontario

M1K 5H4, Canada

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard,

Kennesaw, GA 30152