

### Re: SRX-Pro Service v7.1.2.60 Release Notice

October 9, 2020

To all of our customers and partners;

This bulletin is the official notice of the SRX-Pro Service (Pro Setup) **v7.1.2.60** release. Released in conjunction with **VPC v7.1.2.60**.

The new software installation package is now available for download from the i3 website: <a href="http://i3international.com/support/download">http://i3international.com/support/download</a>.

This software version is going to be used in Production as a standard default software version for all standard NVR starting **Tuesday**, **October 13**, **2020**. To continue receiving your NVRs with SRX-Pro v6 or an earlier version of SRX-Pro v7, please speak to your RSM to arrange for a "Special Routing" to be created for your NVRs.

### **New Features:**

Read Social Distancing values from i3Ai v7.1.2.46. (#29055)
See i3Ai v7.1.2.46 release bulletin for more information about the Social Distancing feature.

## Improvements:

The number of mobile connections increased to 20 for all systems, regardless of licensing (including U10/U12 SRX-Pro Core systems. (#28551)

The following applications are considered "mobile": SRX-Pro Mobile app, CMS Mobile app, CMS Web. Mobile connection licenses are used as follows:

- o CMS Web and CMS Mobile app 1 license per channel (Video Streaming)
- o SRX-Pro Mobile app 1 licenses per server

Note: The number of remote connections for SRX-Pro Setup and VPC remains unchanged.

- Include PAC Converter v.3.3.2.10 (#30215)
- Remove the port range limitation (previously 1 to 65535) from Add/Edit camera window when adding cameras manually. (#29751)

#### Fixed issues:

- Lost configuration settings issue resolved (#30583)
- Duplicate IP address in IPcamera.json (#30582)
- Issue with the i3 PoE switch restart sync resolved (#29631)
- i3Ai camera page:
  - Delay in loading i3Ai camera information resolved (#29145)
  - Link all i3Ai cameras feature issue resolved (#28908)
- System Time sync issue resolved (#28510)
- When Server ID is changed and space is added, connection issue has been resolved (#28206)

### Limitations:

English-language support only

## **13 INTERNATIONAL TECHNICAL BULLETIN**

201009-SW-02

CONTACT US

### www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152



## SRX-Pro v7.1 Compatibility Table.

Note: For i3 application compatibility, refer to i3's Software Compatibility Chart

i3 Application / Device	Compatibility
SRX-Pro configuration	v.3.3.X.X to v.7.0.2.X
UIO8	UIO8 Firmware v2.3.0 to v2.3.6
CMS Web	CMS v5.9.2.44 or higher
PACDM	PACDM v7.23.2.8
	PAC Converter v3.2.2.10
VPC	VPC v7.1.2.49 or higher
i3Ai	i3Ai v7.1.2.46
ACT	Annexxus Configuration Tool v1.7.2.6. and higher

## **About Version:**

Version 7.1.2.60

Build Date: September 7, 2020

Please contact technical support if you have any questions or issues.

Email: <a href="mailto:support@i3international.com">support@i3international.com</a>

Tel.: 1.877.877.7241

Live Chat: http://i3chat.i3international.com/chat

# **i3 INTERNATIONAL TECHNICAL BULLETIN**

201009-SW-02

**CONTACT US** 

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776 CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152