

INTELLIGENT VIDEO DRIVING PROFIT

Re: SRX-Pro Server v7.3.2.88 Release Notice

January 22, 2024

To all of our customers and partners;

This bulletin is the official notice of the SRX-Pro Server **v7.3.2.88 (Build 19-Jan-2024)** release. The new software installation package is now available for download from the i3 website: <u>https://i3international.com/support/download</u>.

Effective **Monday, January 22, 2024** this release package will be used as the default Production software version for all standard NVRs. To continue receiving your NVRs with an earlier version of SRX-Pro/VPC v7, please speak to your RSM to arrange for a "Special Routing" to be created for your NVRs.

New Features:

- SRX-Pro Setup now available in French (Français). (<u>#68605</u>) To switch between English/French interface, log into the SRX-Pro Setup, click on your username in the top right-hand corner and open the Language menu.
- Server ID : i3-DEMO2 i3admin → Э English Language > Français SH SAVE
- Support hardware watchdog function for U16 (<u>#68605</u>)
- Support manual camera name sync from SRX-Pro Setup to i3Ai Setup if the camera name is changed. (<u>#68410</u>) (Note: The SRX-Pro channel name is already synced automatically to i3Ai whenever Ai is enabled on the camera in the SRX-Pro Setup.)
- Support *.csv camera list Export function in SRX-Pro Setup > List (#44967 / PAR#135)

All (38) 🔻	0 selected		Search	Q	Columns 🕶	EDIT	DELETE
	Channel #	Camera name	Model name	IP address	Resolution	FI	PS Status
	1	CH1, M77R2 (5MP) Main Entrance	M77R2 AUDIO	172.21.2.41	2592x1944	▼ 7	Connected
~ 🗆		LD16 (172.21.1.116)					

A															
1 Channel	# Camera name	Model name	IP address	Adapter	Port	Input	Resolution	Streaming Option	FPS	Sub resolution	Sub FPS	MAC	Status	PTZ	Audio
2	1 CH1, M77R2 (5MP) Main Entrance	M77R2 AUDIO	172.21.2.41	i30EM	80	1	2592x1944	UDP	7	704x480	10	18:F8:7A:07:60:B0	Connected	Disabled	NONE
3	2 CH2, LD16-IN2, Am57 (2MP) Main Entrance	LD16	172.21.1.116	ONVIF	80	2	1920x1080	UDP	7	704x480	10	18:f8:7a:08:61:d2	Connected	Enabled	NONE
4	3 CH3, LD16-IN1, Am51 Unit 16 Walkway	LD16	172.21.1.116	ONVIF	80	1	1920x1080	UDP	7	704x480	10	18:f8:7a:08:61:d2	Connected	Enabled	NONE
5	4 CH4, LD16-IN3, Am73 (5MP) Parking	LD16	172.21.1.116	ONVIF	80	3	2048x1536	UDP	20	704x480	10	18:f8:7a:08:61:d2	Connected	Enabled	NONE

i3	INTERN A	ATIONAL	TECHNICAL	BULLETIN
----	-----------------	---------	-----------	----------

CONTACT US

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

240122-SW-01

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152



INTELLIGENT VIDEO DRIVING PROFIT

Improvements:

- Change the rules for the "CPU usage is high" alert. Display the alert only if the CPU remains high for over 1 minute (to exclude momentary CPU spikes during initial startup). (<u>#64437</u> / <u>PAR#160</u>)
- Change the format of the export setting file from *.zip to *.i3z to prevent confusion. (#64731 / PAR#158)
- Ignore the bandwidth limitation setting when connecting via localhost VPC (#46311 / NCR#1769)
- Apply changes to i3 default settings: (#65329)
 - Replace a list of suggested NTP servers with two: time.windows.com and time.google.com
 - Change Panic backup destination to "Local" from "CD/DVD", as optical drives are no longer included.
 - Change the default Recording Type to "Sequential"
 - Support additional destination for LPR_CSV export (#64340)
- Show "Unsupported browser" webpage when launching SRX-Pro Server in IE (default web browser on legacy units) (<u>#64192</u>)

New Features in testing stage

- Support new i3Ai features (Engagement and Trajectory Anomaly) (<u>#67250</u>) i3Ai required, subject to licensing fees. Please contact your sales rep to learn more.
- Add pop-in installation instruction guide for FACE Management (FR8) (#65203)
- Show recently visited SRX-Pro setup pages in i3Host Home Page under "Recently Visited" (#64425)

Fixes

- Add camera page: support horizontal scroll on low resolution screens (#65864)
- Fix failed schedule upload resume (on CMS) after SRX-Pro restart. (#65250)
- On units without D:\ partition, write logs to C:\i3temp instead (#63853)
- SRX-Pro not recognizing video data older than 2 years (#69122)
- Improve stability and performance of Live/search via Relay server (#68771)
- Various fixes and performance improvements (<u>#64714, #68915, #69062</u>)

VPC v7.3 Compatibility Table.

Note: For i3 application compatibility, refer to i3's Software Compatibility Chart

i3 Application / Device	Compatibility				
VPC	VPC v7.3.2.0 and higher				
PACDM	PACDM v7.26.2.137 or higher				
PAGDIM	PAC Converter v3.7.2.80 or higher				
i3Ai	i3Ai v7.3.2.90 or higher				
CMS	CMS v6.5.2.0 and higher				

About Version:

Version 7.3.2.88 Build Date: Jan 19, 2024

i3 INTERNATIONAL TECHNICAL BULLETIN

CONTACT US

CANADA

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

240122-SW-01

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152



Release History

Version	Release Type	Build date
7.3.2.88 (this version)	Production	January 19, 2024
7.3.2.85	Interim	December 29, 2023
7.3.2.60	Interim	September 29, 2023
7.3.2.47	Production	July 19, 2023
7.3.2.45	Interim	July 14, 2023
7.3.2.16	Production	March 16, 2023
7.3.2.12	Interim	February 28, 2023
7.3.2.0	Production	January 16, 2023

Please contact technical support if you have any questions or issues. Email: support@i3international.com Tel.: 1.877.877.7241

i3 INTERNATIONAL TECHNICAL BULLETIN

CONTACT US

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152

240122-SW-01

