

INTELLIGENT VIDEO DRIVING PROFIT

May 30, 2024

Re: PACDM v7.27.2.0 Release Notice


To all of our customers and partners.

This bulletin is the official notice of the PACDM v7.27.2.0 release.


Effective **Monday, June 3, 2024** this release package is used as the default Production software version for all NVRs. The software installation package is now available for download from the i3 website: <u>https://i3international.com/support/download</u>

New Features:

• i3Ai Service Timer new widget: Leaderboard Previous Day Tips (#66524)



 Change DT gap to PD DT gap (DT = DriveThrough; PD = Previous Day) (<u>#66370</u>) Support show/hide items on the Current day widget through PVMSetup.cfg config editing (<u>#66336</u>)



i3 INTERNATIONAL TECHNICAL BULLETIN

CONTACT US

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

240530-SW-01

USA

i3 America (Nevada) Inc.


4001 Cobb International Boulevard, Kennesaw, GA 30152





Improvements:

Support PVM on the Main Monitor. Allow minimizing the PVM window. Only one type of PVM per monitor is supported. (<u>#69530</u>)



elocity Dashboard	Velocity Leaderboard	i3Ai Service Timer	+

- Update Parser version and select templates (#67400)
- Support LPR database and search without LPR license, since H59B7 is an Edge LPR camera and requires no separate LPR license (#67483)
- Hide POS information on VTS PVM drive through lane graphic widget if there are no PAC settings for menu areas (#69408)
- Verifone Commander template: Include updated V1.12_Verifone_Commander template (#69940)

Fixed issues:

- Xpient template fixes (<u>#69986</u>, <u>#70011</u>, <u>#70059</u>)
- I3Ai Service Timer PVM font size change fix (#68376)

i3 INTERNATIONAL TECHNICAL BULLETIN

CONTACT US

CANADA

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

240530-SW-01

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152



Version	Build date
7.27.2.0 (this version)	March 11, 2024
7.26.2.137	March 14, 2023
7.26.2.128	January 12, 2023
7.26.2.109	November 4, 2022
7.26.2.95	August 2, 2022
7.26.2.89	June 29, 2022
7.26.2.79	May 6, 2022
7.26.2.56	February 28, 2022
7.26.2.38	November 15, 2021
7.26.2.30	October 15, 2021

Please contact our Technical Support team if you have any questions or issues. Email: <u>support@i3international.com</u>

Tel.: 1.877.877.7241

i3 INTERNATIONAL TECHNICAL BULLETIN

CONTACT US

www.i3international.com

Toll free: 1.866.840.0004 Tel: 416.261.2266 Fax: 416.759.7776

CANADA

i3 International Inc.

780 Birchmount Rd, Unit 16 Toronto, Ontario M1K 5H4, Canada

240530-SW-01

USA

i3 America (Nevada) Inc.

4001 Cobb International Boulevard, Kennesaw, GA 30152