



Re: SRX-Pro Service v7.1.2.131 Release Notice

July 5, 2021

To all of our customers and partners;

This bulletin is the official notice of the SRX-Pro Service (Pro Setup) v7.1.2.131 (Build 7-Jun-2021) release. Please note that this is the last and final SRX-Pro v7.1 package. No further improvements/fixes are anticipated for this SRX-Pro version series. The next SRX-Pro release will be moving to v7.2.2.X version.


**Important:** For the best performance and stability of your system, i3 strongly recommends upgrading all Servers running the earlier versions of SRX-Pro v7.0.2.X and SRX-Pro v7.1.2.X to this current release (v7.1.2.131).

Failure to upgrade to SRX-Pro v7.1.2.131 may, in rare cases, result in video recording stoppages/loss.

The new software installation package is now available for download from the i3 website: <http://i3international.com/support/download>.

This software version is going to be used in Production as a default software version for all standard NVR starting **Tuesday, July 5, 2021**. To continue receiving your NVRs with an earlier version of SRX-Pro v7, please speak to your RSM to arrange for a "Special Routing" to be created for your NVRs.

**Fixed issues:**

- License Plate Recognition installation is included in the software package. Valid LPR license is required for use; updated End User License Agreement (#40136)
- Speed up recording validation process in the (rare) instances of \*.idx file corruption. (#40013)
- Disable Auto-discovery to prevent the (rare) instances of random server reboot in specific customer environment (very high number of cameras + low-bandwidth network). To add newly connected cameras, click the **REFRESH** button in the **Add** tab (#40137). 
- Critical WatchDog improvement to resolve the (rare) instances of random SRX-Pro service reboot. (#40323)

**Limitations:**

- English-language support only

**SRX-Pro v7.1 Compatibility Table.**

**Note:** For i3 application compatibility, refer to i3's [Software Compatibility Chart](#)

i3 Application / Device	Compatibility
SRX-Pro configuration	v.3.3.X.X to v.7.1.2.X
UIO8	UIO8 Firmware v2.3.0 to v2.3.6
CMS Web	CMS v5.10.2.X or higher
PACDM	PACDM v7.25.2.X or higher PAC Converter v3.5.2.17 or higher
VPC	VPC v7.1.2.131 or higher
i3Ai	i3Ai v7.1.2.X or higher
ACT	Annexus Configuration Tool v1.7.2.X or higher

CONTACT US

[www.i3international.com](http://www.i3international.com)

Toll free: 1.866.840.0004  
Tel: 416.261.2266  
Fax: 416.759.7776

CANADA

**i3 International Inc.**

780 Birchmount Rd, Unit 16  
Toronto, Ontario  
M1K 5H4, Canada

USA

**i3 America (Nevada) Inc.**

4001 Cobb International Boulevard,  
Kennesaw, GA 30152



INTELLIGENT VIDEO DRIVING PROFIT

**About Version:**

Version 7.1.2.131

Build Date: June 7, 2021

Please contact technical support if you have any questions or issues.

Email: [support@i3international.com](mailto:support@i3international.com)

Tel.: 1.877.877.7241

Live Chat: <http://i3chat.i3international.com/chat>

CONTACT US

**[www.i3international.com](http://www.i3international.com)**

Toll free: 1.866.840.0004

Tel: 416.261.2266

Fax: 416.759.7776

CANADA

**i3 International Inc.**

780 Birchmount Rd, Unit 16

Toronto, Ontario

M1K 5H4, Canada

USA

**i3 America (Nevada) Inc.**

4001 Cobb International Boulevard,

Kennesaw, GA 30152